

Piper PA-34 (Seneca) Series Aeroplanes

AD/PA-34/14

Fuel Line Chafing - Inspection

10/74

Applicability: Model PA-34-200 with S/Nos. 34-7250001 to 34-7450209.

Document: Piper SB No. 429.

Compliance: Within 100 hours time in service after 31 October 1974.