
AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/PA-34/15.

Piper PA-34 (Seneca) Series Aeroplanes

AD/PA-34/15

Outer Wing Spars - Inspection

11/2008

Requirement: CANCELLED.

This AD is cancelled on 23 October 2008.

Background: This AD specified a once-only inspection of the outer wing spar. The inspection was not based on a Piper service document. USA AD 74-19-01 specified the same inspection. This AD and 74-19-01 required compliance within 10 hours time in service after September 1974 so the AD is no longer required.



David Villiers
Delegate of the Civil Aviation Safety Authority

9 September 2008