
AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/PA-34/26.


Piper PA-34 (Seneca) Series Aeroplanes

AD/PA-34/26 Fuel Line - Inspection and Modification 11/2008

Requirement: CANCELLED.

This AD is cancelled on 23 October 2008.

Background: This unique Australian AD specified inspection and modification of fuel lines in accordance with Piper SB No. 584. Compliance was required within 100 hours time in service after February 1978. The AD is no longer required.



Charles Lenarcic
Delegate of the Civil Aviation Safety Authority

11 September 2008