

---

## AIRWORTHINESS DIRECTIVE

---

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/PA-38/9.

---

### Piper PA-38 (Tomahawk) Series Aeroplanes

**AD/PA-38/9                      Slick Magneto/Condenser - Replacement                      13/2008**

Requirement:    CANCELLED.

This AD is cancelled on 18 December 2008.

Background:    This unique Australian AD specified replacement of Slick magnetos and condensers in accordance with Lycoming SB No. 432 or Piper SB No. 620. Compliance was required no later than March 1979. The AD is no longer required.



James Coyne  
Delegate of the Civil Aviation Safety Authority

24 October 2008