
AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/PA-44/16.

Piper PA-44 (Seminole) Series Aeroplanes

AD/PA-44/16

Ailerons

4/2009

Requirement: CANCELLED.

This AD is cancelled on 9 April 2009.

Background: This unique Australian AD specified periodic inspection of both ailerons for cracking of the nose ribs and hinge brackets. Inspection was required at intervals not exceeding 500 hours time in service. This AD was not based on a Piper service document. Using an AD to mandate this inspection is no longer warranted.



David Punshon
Delegate of the Civil Aviation Safety Authority

6 February 2009