
AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/PA-46/3.

Piper PA-46 (Malibu) Series Aeroplanes

AD/PA-46/3

**Fuel Supply Line Replacement
and Wing Rib Modification**

4/2009

Requirement: CANCELLED.

This AD is cancelled on 9 April 2009.

Background: This unique Australian AD specified once-only replacement of the fuel supply line, and modification of a wing rib, in accordance with Piper SB No. 792 within 100 hours time in service after November 1984. The AD is no longer required.



James Coyne
Delegate of the Civil Aviation Safety Authority

16 February 2009