
AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/PA-46/7.

Piper PA-46 (Malibu) Series Aeroplanes

AD/PA-46/7 Oxygen System Electrical Wiring Rerouting 4/2009

Requirement: CANCELLED.

This AD is cancelled on 9 April 2009.

Background: This unique Australian AD specified re-routing of the electrical wiring in the oxygen system in accordance with Piper SB No. 791. Compliance was required within 100 hours time in service after December 1984. The AD is no longer required.



James Coyne
Delegate of the Civil Aviation Safety Authority

16 February 2009