
AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/PA-46/14 Amdt 2.

Piper PA-46 (Malibu) Series Aeroplanes

**AD/PA-46/14
Amdt 2**

Aileron Cable Routing

4/2009

Requirement: CANCELLED.

This AD is cancelled on 9 April 2009.

Background: This unique Australian AD specified inspection of the routing of aileron cables in accordance with Piper SB No. 863A within 100 hours time in service after May 1996. The AD is no longer required.



David Punshon
Delegate of the Civil Aviation Safety Authority

3 February 2009