
AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/PA-46/25.

Piper PA-46 (Malibu) Series Aeroplanes

AD/PA-46/25

Fuselage Rivet Installation

4/2009

Requirement: CANCELLED.

This AD is cancelled on 9 April 2009.

Background: This unique Australian AD specified inspection, and installation if necessary, of rivets in the fuselage in accordance with Piper SB No. 959 at the next scheduled inspection for maintenance release issue after July 1993. The AD is no longer required.



David Punshon
Delegate of the Civil Aviation Safety Authority

3 February 2009