

Pilatus PC-12 Series Aeroplanes

**AD/PC-12/8
Amdt 1**

Executive Cabin Layout

9/98

- Applicability: Lavatory Wall Modification: All PC-12 and PC-12/45 aircraft, MSN 101 up to and including MSN 180, which have an executive cabin layout.
- Passenger Seat Configuration Modifications: All PC-12 and PC-12/45 aircraft, MSN 101 up to and including MSN 171, which have an executive cabin layout.
- Requirement: Modify in accordance with Pilatus Aircraft Service Bulletin (SB) 25-003 Revision 1.
- Note: FOCA Switzerland AD HB 97-249A refers.*
- Compliance: Unless already accomplished in accordance with SB 25-003, before 13 September 1998.
- This amendment becomes effective on 13 August 1998.
- Background: In order to comply with the Head Injury Criteria requirements of FAR 23.562 (c)(5), this Directive requires modification of the executive cabin type layout.
- Amendment 1 is issued in response to revision of the FOCA AD which introduces a revised Requirement document which clarifies certain requirements.
- The original issue of this airworthiness directive became effective on 2 July 1997.