

Gulfstream (Rockwell) 114 Series Aeroplanes

AD/ROCK-114/3

Cabin Air Vent - Modification

5/78

Applicability: All models with S/Nos. listed in requirement document.

Document: Rockwell SB No. SB-114-6.

Compliance: Unless already accomplished, within 100 hours time in service after 30 June 1978.

Note: When this Directive has been complied with the operator may apply to a Regional Airworthiness Office of the Department for the withdrawal of the flight manual "P" amendment to para. 3.4.