

SAAB Safir Series Aeroplanes

AD/SAAB/2

Fuel Pump Actuating System

5/86

Applicability: Model SAAB Safir 91B, 91B-2, 91C and 91D.

Requirement: Action in accordance with SAAB SB 91.4.003.

Note: Swedish AD No 1-017 refers.

Compliance: Within 100 hours time in service after 31 May 1986.

Background: The manufacturer has received a report of the cable assembly of the manually actuated fuel pump, failing during operation in an emergency situation.