
AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/SM-205/13.

SIAI Marchetti S205 and S208 Series Aeroplanes

AD/SM-205/13 Engine Operating Limitation - Installation of 6/2009
Placard and Modification of Tacho Marking

Requirement: CANCELLED.

This AD is cancelled on 4 June 2009.

Background: This unique Australian AD raised in 1971 against SIAI Marchetti Service Bulletin (SB) SB 205B18A required a modification by installation of a placard indicating revised engine RPM limitations and marking of Tachometer.

Compliance was: Before 30 April 1971.

This AD has been sufficiently promulgated for the affected aircraft to have been modified by now; therefore this AD is considered to be no longer required.



James Coyne
Delegate of the Civil Aviation Safety Authority

24 April 2009