

---

## AIRWORTHINESS DIRECTIVE

---

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/SWSA226/49 Amdt 1.

---

### Fairchild (Swearingen) SA226 and SA227 Series Aeroplanes

**AD/SWSA226/49  
Amdt 1**

**Fuel Vent Line and Electrical Wire  
Bundle Support Clamps - Installation**

**6/2009**

Requirement: CANCELLED.

This AD is cancelled on 4 June 2009.

Background: This unique Australian AD raised in 1985 against Fairchild Aircraft Corporation Service Bulletin (SB) SB 226-008 and SB 227-28-001 required a modification by installation of support clamps to prevent chaffing between the fuel vent system line and electrical wire bundle located with the wing flap well.

Compliance was: Within 30 hours TIS after 31 January 1985.

This AD has been sufficiently promulgated for the affected aircraft to have been modified by now; therefore this AD is considered to be no longer required.



James Coyne  
Delegate of the Civil Aviation Safety Authority

24 April 2009