## COMMONWEALTH OF AUSTRALIA CIVIL AVIATION SAFETY AUTHORITY SCHEDULE OF AIRWORTHINESS DIRECTIVES

Aerospatiale (Socata) TB9 and TB10 (Tobago) Series Aeroplanes

AD/TB10/16	Lower Engine Cowl Carburettor Air Supply 3/91
Applicability:	All TB9 & TB10 series aircraft from S/No's 1 to 944 inclusive fitted with lower cowling carburettor air supply.
Requirement:	Action in accordance with the technical requirements of DGAC AD 90-240 (A).
Compliance:	As specified in the Requirement Document with revised effective date of 31 March 1991.
Background:	The lower engine cowl `NACA' fitting can be damaged if the supply hose clamp is overtightened. If the fitting is damaged the intake hose could come loose possibly restricting engine operation.