

Aerospatiale (Socata) TB20 (Trinidad) Series Aeroplanes

---

**AD/TB20/20                      Horizontal Stabiliser Balance Weight                      4/91 DM**

Applicability:    Model TB20 and TB21 series with serial numbers 1 through 1030.

Requirement:    Action in accordance with Alert SB 57.

Compliance:    Within 25 hours time in service after 13 February 1991.

Background:    This Directive requires an inspection to determine whether both attaching nuts of the horizontal stabilizer balance weight are within the required safety dimension. Detachment of balance weight may lead to a dangerous flutter condition.