
AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, this AD is revoked by CASA ADCX 010/13.

Aerospatiale (Socata) TBM 700 Series Aeroplanes

AD/TBM 700/35

Flight Controls - Flap Actuator

11/2013

Requirement: CANCELLED.

This AD is cancelled on 27 May 2013.

Background: A State of Design airworthiness directive issued on or after 1 October 2009 is defined as an airworthiness directive per CASR Part 39.001A. The requirements of this airworthiness directive which referred to DGAC (French) AD F-2004-134, dated 4 August 2004 have been superseded by EASA AD 2013-0104, issued on 13 May 2013.