

Aerostar (Piper/Ted Smith) 600 and 700 Series Aeroplanes

AD/TSA-600/13 **Low Fuel Warning Light - Modification** **4/78**

Applicability: All models to S/No. 0474.

Document: 1. Ted Smith SB No. SB600-71; or
 2. FAA AD 77-26-04; or
 3. FAA AD 79-01-05.

Compliance: Within 100 hours time in service after 30 April 1978.