

Victa and A.E.S.L. Airtourer Series Aeroplanes

AD/VAT/21 Fuel Tank Retention Buttons - Modification 11/64

Applicability: Victa Airtourer 100 and 115 with S/Nos. 1 to 75.

Document: Victa SB No. 44.

Compliance: Within 100 hours time in service after 20 November 1964.