

Victa and A.E.S.L. Airtourer Series Aeroplanes

AD/VAT/26

Wing Walkway - Modification

11/66

Applicability: Victa Airtourer 100 and 115.

Document: Victa SB No. 64.

Compliance: Within 150 hours time in service after 7 November 1966.