

Cessna 188 (Agwagon) Series Aeroplanes

**AD/CESSNA 188/3
Amdt 1**

Main Undercarriage Legs

2/69

Applicability: All models not fitted with spring leg P/No. 1641007.

Requirement: Inspect the main undercarriage spring legs for cracking in the vicinity of the bend adjacent to fuselage attachment points using the magnetic particle method.

Compliance: At intervals not exceeding 300 hours time in service.